




# MOTOR, DPDT, PWM, ART CONTROLLER, POWER SUPPLY



MOTOR TURNS, HITS THE LIMIT SWITCH, ART CONTROLLER STOPS FOR A PERIOD OF TIME, THEN STARTS THE MOTOR AGAIN. THIS CYCLE REPEATS.



*[Handwritten signature]*

S.C.

6/01/2019

MAKERMOTOR